

The manufacturer may use the mark:



Revision 3.0 September 27, 2022 Surveillance Audit Due June 1, 2025



Certificate / Certificat Zertifikat / 合格証

ASC 1301001 C005

exida hereby confirms that the:

Series 551 and 553 Pilot Operated Inline Spool Valves

ASCO Numatics Lucé, France

Have been assessed per the relevant requirements of:

IEC 61508 : 2010 Parts 1-2

and meets requirements providing a level of integrity to:

Systematic Capability: SC 3 (SIL 3 Capable)

Random Capability: Type A, Route 2_H Device

PFH/PFD_{avg} and Architecture Constraints must be verified for each application

Safety Function:

The Valve will move to the designed safe position when deenergized within the specified safety time.

Application Restrictions:

The unit must be properly designed into a Safety Instrumented Function per the Safety Manual requirements.



Assessor atina

Certifying Assessor

Page 1 of 2

Series 551 and 553 Pilot Operated Spool Valves

Certificate / Certificat / Zertifikat / **合格証** ASC 1301001 C005

Systematic Capability: SC 3 (SIL 3 Capable) Random Capability: Type A, Route 2_H Device

PFH/PFD_{avg} and Architecture Constraints must be verified for each application

Systematic Capability :

These products have met manufacturer design process requirements of Safety Integrity Level (SIL) 3. These are intended to achieve sufficient integrity against systematic errors of design by the manufacturer.

A Safety Instrumented Function (SIF) designed with these products must not be used at a SIL level higher than stated.

Random Capability:

The SIL limit imposed by the Architectural Constraints must be met for each element. This device meets *exida* criteria for Route 2_{H} .

Applications

Series 551 & 553 Spool Valves 3/2, NC, De-energize To Trip (DTT) and 5/2 (DTT)

IEC 61508 Failure Rates in FIT¹

| Failure Category | λ_{SD} | λ _{su} | λ_{DD} | λ_{DU} |
|--|-----------------------|-----------------|----------------|-----------------------|
| 3/2 Single, NC, DTT, <2W Coil | 0 | 209 | 0 | 329 |
| 3/2 Single, NAMUR, NC, DTT, <2W Coil | 0 | 304 | 0 | 378 |
| 3/2 Single, NF Operator, NC, DTT, 9-16 W Coil | 0 | 572 | 0 | 316 |
| 3/2 Single, NAMUR, NF Operator, NC, DTT, 9-16 W Coil | 0 | 666 | 0 | 365 |
| 3/2 Redundant, NC, DTT, <2W Coil | 0 | 187 | 0 | 369 |
| 5/2 Single, DTT, <2W Coil | 0 | 234 | 0 | 378 |
| 5/2 Single NAMUR, DTT, <2W Coil | 0 | 256 | 0 | 432 |
| 5/2 Single, NF Operator, DTT, 9-16 W Coil | 0 | 597 | 0 | 365 |
| 5/2 Single, NAMUR, NF Operator, DTT, 9-16 W Coil | 0 | 618 | 0 | 419 |
| 5/2 Redundant, DTT, <2W Coil | 0 | 197 | 0 | 418 |
| Adder for Coils ² 9-16 Watts | 0 | 299 | 0 | 0 |
| Adder for Class H Coils 16–30 Watts | 0 | 729 | 0 | 0 |
| 3/2 Single, Air Operated, NC, DTT | 0 | 268 | 0 | 249 |
| 5/2 Single, Air Operated, DTT | 0 | 195 | 0 | 328 |

¹ FIT = 1 failure / 10^9 hours

SIL Verification:

The Safety Integrity Level (SIL) of an entire Safety Instrumented Function (SIF) must be verified via a calculation of PFH/PFD_{avg} considering redundant architectures, proof test interval, proof test effectiveness, any automatic diagnostics, average repair time and the specific failure rates of all products included in the SIF. Each element must be checked to assure compliance with minimum hardware fault tolerance (HFT) requirements.

The following documents are a mandatory part of certification:

Assessment Report: ASC 13/01-001 R003 V2R1 (or later)

Safety Manual: V9629 Rev JC (or later)



Sellersville, PA 18960

80 N Main St

exida

T-061, V5R2