



Emerson Automation Solutions
19200 Northwest Freeway
Houston, TX 77065
USA

T 1 (281) 477 4100
F 1 (281) 477 2801
www.emerson.com

September 30, 2019

Product Advisory 082319_1_JAB (ECO ELEC262)

Bettis M2CP Electric Actuator with Controlinc 320B Card

Subject: 320B firmware release to Ver 3.61 (M2CP), prior Ver 3.60

Affected Product: 320B cards in M2CP
Part Numbers: VA84605 and VA84605-2

Changes:

1. On loss of analog input, Stay-Put feature is functional. Previously, when this feature was selected, the actuator could go to fully open or fully close.
2. Full stroke and Partial stroke Tests have been incorporated.
3. Default value for "Control Bandwidth" changed from 2% to 1%. Can still change to other during calibration is desired.
4. Support for new features incorporated in DCMLink 2.3

Production Release Date:

September 26, 2019

Affected literature: N/A