



Emerson Automation Solutions
19200 Northwest Freeway
Houston, TX 77065
USA

T 1 (281) 477 4100
F 1 (281) 477 2801
www.emerson.com

January 9, 2020

Product Advisory 091619_1_pw (ECO ELEC288)

TEC2 Electric Actuator Firmware Update

SUBJECT: CCM/LDM firmware upgrade from Version 1.0.8 to Version 1.1.0

PRODUCT CONFIGURATIONS: Brands: Bettis or EIM
Models: TEC2
Model/Series 500

FIRMWARE CHANGES: Added storing of adaptive coast value to FLASH and read the stored values at startup to restore the information at customer sites at startup.

PRODUCTION RELEASE DATE: January 10, 2020

AFFECTED LITERATURE: N/A